

Attic Trac Service Bulletin # 700401

During installation, should you find that a vertical truss member obstructs the placement of the rail supports, try the following:

- Move previously attached rail supports backwards or forwards to assure clearance of the obstruction.
- Angle the rail support enough to miss the obstruction and yet still allow the rail to be attached.

